



THE DIAMONDS SUBDIVISION SECTION ONE
Plat Book 11, page 856
N 85°01'26" E 1090.06'

SW 1/4, SE 1/4
SEC. 9, T44N, R12W

SW 1/4, SW 1/4
SEC. 10, T44N, R12W

Tract 1 of
MOSEERS SUBDIVISION
Plat Book 11, page 829

NW 1/4, NW 1/4
SEC. 15, T44N, R12W

EMERALD LANE
N 82°07'54" E
627.50'

ONYX DRIVE

IKON DRIVE

EDGEWOOD DRIVE
(Right-of-way Widths Vary)

STATE OF MISSOURI }
COUNTY OF COLE } ss
Filed for record 26 day of August, 1996
at 1 O'clock and 30 Minutes M.,
recorded in Book 11, Page 858.

Larry D. Rademan, Recorder
Larry D Rademan
Deputy

RESTRICTIONS RECORDED IN
BOOK , PAGE

Document No. _____


Central Missouri Professional Services, Inc.
ENGINEERING - SURVEYING
2500 E. McCARTY Phone (573) 634-3455
JEFFERSON CITY, MISSOURI 65101 FAX (573) 634-8898

TITLE **THE DIAMONDS SUBDIVISION SECTION TWO**
SE Sec 9, NW Sec 15, NE Sec 16, T44N, R12W, Cole Co. MO

FOR **Greenco Development Company, L.C.**

DATE 5/24/96	DRN. BY C.F.B.	SCALE 1"=50'	BOOK 689
REV. DATE 7/19/96	CKD. BY	SHEET 2 of 2	JOB NO. 95-294

- Notes:
1. Set 1/2" Iron Pin with cap at all Property Corners unless otherwise noted.
 2. This Property is NOT within a flood hazard zone as indicated on the Department of Housing and Urban Development Map, Federal Insurance Administration, Dated: October 6, 1981.
 3. LOT No.'s. 40, 41, 44, 45, and 48 SHALL HAVE NO DRIVEWAY ACCESS TO EDGEWOOD DRIVE.



COMPLETED

SUBD. 400-03 400II

C:\M\MOSEERS\GREEN\SEC2-F-2 Thu Aug 15 14:35:10 1996